

# Vault Light Removal


60 West 22<sup>nd</sup> Street


New York, NY 10010



# Proposed Work







# Reasons For Proposed Removal

## Condition of Vault Lights











# Water Penetration







# Constant Trip Hazard





# Concrete as the Pattern







# 20 West 22<sup>nd</sup> Street





## ➤ Overview:

- Historical Vault Lights were discovered underneath the diamond plate covers in the sidewalk of 60 W 22<sup>nd</sup> Street.
- I have proposed the removal of diamond plate covers and vault lights with the subsequent pouring of new concrete (3000 or 3500 PSI).
- Detrimental conditions of vault lights, water penetration and trip hazard were three of the main reasons presented for the proposed work.
- I have also established that concrete is the common pattern within the district.
- Diamond plate covers do not signify an essential aspect of the building nor the neighborhood.
- Vault lights, which are commonly found in SOHO, were not found within this district.