

**Amendment to Application for 28-30 East 92nd Street:
Change in Brownstone Repair and Replacement Scope
Due to Field Conditions**


Summary of Application




Front View from E 92nd Street



View from Far Corner of Madison Ave. & E 92nd Street



Existing



Proposed

Nightingale-Bamford School
 Facade of 28-30 East 92nd Street, New York



Existing



Proposed

Proposed Front Elevation



Nightingale-Bamford School
Facade of 28-30 East 92nd Street, New York

Brownstone Field Conditions



PHOTO DOCUMENTATION

Nightingale-Bamford School
Facade of 28-30 East 92nd Street, New York

BRB Architects

October 20, 2015



PHOTO DOCUMENTATION

Nightingale-Bamford School
Facade of 28-30 East 92nd Street, New York

BRB Architects

October 20, 2015




PHOTO DOCUMENTATION

Nightingale-Bamford School
Facade of 28-30 East 92nd Street, New York

BRB Architects

October 20, 2015



PHOTO DOCUMENTATION

Nightingale-Bamford School
Facade of 28-30 East 92nd Street, New York

BRB Architects

October 20, 2015

Video Link

B Scope of Brownstone Repair & Replacement Maximizing Retention of Original Material and Substrates



LEGEND

- Pieces that must be replaced with precast
- Pieces that must be taken down, scratch-coated and fully patched, and reinstalled
- Pieces that must be taken down, partially patched, and reinstalled
- Pieces that must be taken down and reinstalled
- Pieces that must be scratch-coated and fully patched in place
- Pieces to remain in place
- Area where original material was lost, to be replaced with precast

Nightingale-Bamford School
Facade of 28-30 East 92nd Street, New York

Proposed Solution



LEGEND

- Pieces that must be replaced with precast
- Pieces that must be taken down, scratch-coated and fully patched, and reinstalled
- Pieces that must be taken down, partially patched, and reinstalled
- Pieces that must be taken down and reinstalled
- Pieces that must be scratch-coated and fully patched in place
- Pieces to remain in place
- Area where original material was lost, to be replaced with precast



A Scope of Brownstone Repair & Replacement per Original Application

B Scope of Brownstone Repair & Replacement Maximizing Retention of Original Material and Substrates

A Scope of Brownstone Repair & Replacement per Original Application



LEGEND

- Pieces that were to be replaced with precast
- Pieces that were to be scratch-coated and fully patched in place
- Pieces that were to be unaltered
- Area where original material was lost, that were to be replaced with precast

Nightingale-Bamford School
 Facade of 28-30 East 92nd Street, New York

BRB Architects

October 20, 2015

B Scope of Brownstone Repair & Replacement Maximizing Retention of Original Material and Substrates



LEGEND

- Pieces that must be replaced with precast
- Pieces that must be taken down, scratch-coated and fully patched, and reinstalled
- Pieces that must be taken down, partially patched, and reinstalled
- Pieces that must be taken down and reinstalled
- Pieces that must be scratch-coated and fully patched in place
- Pieces to remain in place
- Area where original material was lost, to be replaced with precast

Nightingale-Bamford School
Facade of 28-30 East 92nd Street, New York

**C Proposed Scope of 100%
Brownstone Replacement
with Cast Stone
(See Samples)**

